

S305

Dew Point Monitor

Opt. 1 -50 ... +20 °C Td

Opt. 2 -20... +50 °C Td



PLUG & PLAY
Simply connect
your compressed air



DEW POINT MEASUREMENT
-50 ... +50°C Td
depending on
the model



PRECISE MEASUREMENT
± 2°C Td accuracy



ALARM INDICATION
With internal relays
or alarm units