

# S430

## Pitot Tube Flow Meter for Wet Compressed Air

Insertion



**PROCESS MONITORING**  
High accuracy and reliable measurements



**WET AIR MEASUREMENT**  
Directly at the compressor outlet



**COMPRESSOR EFFICIENCY**  
Constant monitoring of the compressor performance



**MOBILE APP**  
For remote configuration and monitoring



**EASY INSTALLATION**  
Under pressure through a ball valve



**NO MECHANICAL WEAR PARTS**  
Stable results in high temperature applications